HMI Touch color Baseline CH-HP-CR Changes history

Release 1.18 03-11-2021

- Fan page modified with 2 fan of two circuit
- Desktop modify, with wateroutlet and waterinlet if regulation probe is inlet or outlet. Moved also SET button on the left of setpoint
- Added Low temperature differential parameter 01.218

Release 1.17 24-05-2021

• Fixed dead zone circuit 2 in setpoint page.

Release 1.14 10-05-2021

- Fixed missing alarm code in alarm page (Removed the "Sets" to save code space and use a dedicated script)
- Fixed missing alarm code in history page
- Fixed circuit 2 compressors in compressors page.


Release 1.12/13 7-05-2020

• Changed IO Configuration Page. Removed the "Sets" to save code space and use a dedicated script.


Release 1.11 13-01-2020

CHANGES:

• Changed Alarms page, added Alarm History button and fixed 2nd line description.



Added Alarms History



Added Generic Regulator custom description

- Improve HMI reaction by changing on timer script of the main page.
- Aligned with PLC application 2.7.15

Used code size:	680B0h (319	KByte)
Free code space:	4FF50h (KByte)
Total code space:	B8000h (KByte)
Aux area 1 used space Aux area 1 free space Aux area 1 total space	: 2D8:	280h 180h 100h	(2912 KByte)
Used data space:	12FD8h (2	KByte)
Free data space:	828h (KByte)
Total data space:	13800h (KByte)

KNOW ISSUE: To update the application a fresh bios upload is needed. Issue under investigation

Release 1.10 26-09-2020

CHANGES: Fied IO IO visualizzation issue

Release 1.07 26-05-2020


- Aligned with PLC application 2.7.8
- Fixed Compressor Timeout alarms
- Added dead zone in quick set page
- Added Alarm configuration option
- Changed user account from level 1 to level 2 (Level 1 id the guest user)
- Changed user account from level 2 to level 3

Release 1.06 13-05-2020

- Aligned with PLC application 2.7.6
 Added Compressor Working Hour alarm

Release 1.04 29-04-2020

- Aligned with PLC application 2.7.4
- Removed Wizard Page
- Review Compressor Page



Release 1.03 15-04-2020

- Aligned with PLC application 2.7.3
 Removed Wizard Page
 Added Alarm detail for inverter errors

Release 1.02 03-04-2020

- Aligned with PLC application 2.7.2
 Compiled for Free Studio Plus 1.2
 New Bios 659.7

Release 1.01 17-02-2020

- Changed ON/OFF Icons Animation
- Fixed visualization issue.
- Added option to disable master communication in order to USE RS485 as slave to upgrade the HMITouch via RS485.

Release 1.00 12-02-2020


CHANGES:

First Release

- 1-Added optimized Alarm Management
- 2-Added Compressor Form
- 3-Added FAN Form
- 4-Added IO Form
- Added LOG Form 5-
- 6-Added Bios settimgs Form

Quick Start guide

Enter in the key logo and enter the installer password "1". The gear icon will apare and You will be able to enter in the service menu.



0f

Су

Λ

0

0

Hour

Start

0.0EV%

V

0

0